
(Revised 2/88)

STATE OF UTAH DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING 355 West North Temple 3 Triad Center, Suite 350 Salt Lake City, Utah 84180-1203 Telephone: (801) 538-5340



DIVISION OF OIL, GAS & MINING

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

1.	Report Time Period:	From (mo./yr.) Jan. 1988 To (mo./yr.) Dec. 1988
2.		riginal notice): <u>m / 021/ 004</u>
3.	Mine Name: Escalant	ce Silver Mine
4.	Mineral(s) Mined:	Silver
5.	Name of Operator or	Company: Hecla Mining Company
	Permanent Address:	D 0 D-11 210
6.	Permanent Address.	Enterprise, Utah 84725
	Commany Depresentat	
7.	Company Representat	tive (or designated operator): Tanara T. Harlin
7.		tive (or designated operator): Tanara T. Harlin Enviromentalist
7.	Name:	tive (or designated operator): Tanara T. Harlin
7.	Name: Title:	tive (or designated operator): Tanara T. Harlin Enviromentalist Enterprise Utah 84725
7.	Name: Title: Address: Phone:	tive (or designated operator): Tanara T. Harlin Enviromentalist P.O. Box 310 Enterprise, Utah 84725 801-439-5355 if any of the above information has changed since
II. <u>MI</u> I	Name: Title: Address: Phone: X Please check previous year	tive (or designated operator): Tanara T. Harlin Enviromentalist P.O. Box 310 Enterprise, Utah 84725 801-439-5355 if any of the above information has changed since

1052V

3.	Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, volume of material moved, and the acreage		
	affected. None		
	Tone		
4.	Briefly describe the reclamation work performed during the past year. This description should include acreage reclaimed, methods employed, and an evaluation of the results.		
	3 Shafts to surface were filled with muck, concrete plug and filled to surface		
	281 6" VCR drill holes were fileed with a 5' concrete plug.		
5.	What was the total unreclaimed acreage at years end? 226		
6.	Briefly summarize mining and reclamation planned for the upcoming year		
	Reclaim portion of canal system		
	Reclaim surface topography of disturbed mine area and reseed		
<u>NOTE</u> :	Section III., "Additional Information" applies only to <u>large mining</u> operations.		
III. ADI	DITIONAL INFORMATION		
1.	An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.		
2.	No significant changes Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.		
IV. SIG	Water monitoring results are reported to the Division of Water NATURE REQUIREMENT Rights each quater.		
I h	ereby certify that the foregoing is true and correct.		
	Signature of Operator: Jana Mail		
	Name (Typed or Print): Tanara T. Harlin		
	Title of Operator: Environmentalist		
	Date: 2-28-89		